


US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>	<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>	
Kalamazoo River/Enbridge Spill	08/07/2012	1850		
<b>4. Unit Name/Designators</b>	<b>5. Unit Leader</b>		<b>6. Operational Period :</b>	
SOS Team #1	<b>Name:</b>	Dan Capone & Joe Victory (START/US EPA)	<b>From:</b>	08/07/2012 0645
	<b>Position:</b>	Operations Section Chief	<b>To:</b>	08/07/2012 1830
<b>7. Personnel Roster Assigned</b>				
<b><u>Name</u></b>	<b>ICS Position</b>		<b>DUTY CELL</b>	
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Timothy Laquerre	SOS#3			
<b>8. Activity Log</b>				
<b>Activity Area</b>	<b>Delta</b>	<b>LAT</b>	<b>LAT</b>	
		<b>Various</b>	<b>Various</b>	
		(DD.MMMM)	(DD.MMMM)	
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>	NA		
	<b>DENSITY OF OIL /SHEEN</b>	NA		
<b>Total Collection Points</b>	NA			
<b>Total Boom Deployed</b>	NA			
<b>Activity</b>	<b><u>START SOTF Team #3 Activity:</u></b>  SOS # 3 conducted oversight of the Agitation Study Team at location 14.8. Team utilized a YUMA/GPS instrument to verify the location of the preinstalled steel box. Sheen net samples, turbidity samples, water samples, core samples and Lsst samples were taken prior to the agitation. Post agitation, turbidity monitoring occurred at the 0:00 hr, 0:15 hr, 0:30 hr, 1:00 hr, 2:00 hr, 4:00 hr and 6:00 hr intervals. Sheen net, water, core and lsst samples were taken.			
<b>Health and Safety Issues</b>	None			
<b>Comments</b>	None			